




Lower Level




8287 Department of Restorative Dentistry
Section of Dental Materials




1st. Floor




8287 Department of Restorative Dentistry Section of Dental Materials



2nd. Floor




8287 Department of Restorative Dentistry
Section of Dental Materials




EMERGENCY STORM SHELTERS

In event of a Tornado Warning everyone should go to the Lower Level **Primary Storm Shelter**

Lower Level



8287 Department of Restorative Dentistry
Section of Dental Materials




EMERGENCY EXIT PLAN

EXIT


IN CASE OF EMERGENCY USE MARKED EXITS

EXIT

Lower Level



8287 Department of Restorative Dentistry
Section of Dental Materials




EMERGENCY EXIT PLAN

EXIT


IN CASE OF EMERGENCY USE MARKED EXITS

EXIT

1st. Floor




8287 Department of Restorative Dentistry
Section of Dental Materials



EMERGENCY EXIT PLAN

EXIT IN CASE OF EMERGENCY USE MARKED EXITS **EXIT**

2nd. Floor



8287 Department of Restorative Dentistry
Section of Dental Materials

