



Lead Service Line Inventory Template

Water System Name: SIUE System ID Number: IL1195550 Current Inventory Date: 04/15/2024 Previous Inventory Date: 04/15/2023 Has Funding Assistance Been Requested?: No

	Service Address	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
		EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
Copper - No Lead Solder (C)		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)									
Copper - Lead Solder (CLS)		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)									
Galvanized (G)		Galvanized (G)					Galvanized (G)	Galvanized (G)									
Lead (L)		Galvanized Requiring Replacemnt (GRR)					Galvanized Requiring Replacemnt (GRR)										
Cast/Ductile Iron or Transite (O)		Lead (L)					Lead (L)										
Plastic - PVC, HDPE, PEX (P)		Cast/Ductile Iron or Transite (O)					Cast/Ductile Iron or Transite (O)										
Plastic - PVC, HDPE, PEX (P)		Plastic - PVC, HDPE, PEX (P)					Plastic - PVC, HDPE, PEX (P)										
Unknown (U)		Unknown (U)					Unknown (U)										
Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)															
1	7001 Lovejoy Library, 30 Hairpin Dr.	N	N	1965	1965	Visual inspection/ Iso. valve rpl.	N/A	O	O	N	N/R	N					
2	7002 Peck Hall, 20 Hairpin Dr.	N	N	1965	1965	Visual inspection/ Iso. valve rpl.	N/A	O	O	N	N/R	N					
3	7003 Science East Building, 40 Hairpin Dr.	N	N	1965	1965	Visual inspection/ Potholed.	N/A	O	O	N	N/R	N					
4	7004 Rendleman Hall, 70 Hairpin Dr.	N	N	1969	1969	Visual inspection/ Iso. valve rpl.	N/A	O	O	N	N/R	N					
5	7005 Morris Unversity Center, 60 Hairpin Dr.	N	N	1966	1966	Construction Records/ Plbg. Print.	N/A	CLS	O	N	N/R	N					
6	7006 Dunham Hall, 50 Hairpin Dr.	N	N	1967	1967	Visual inspection/ Iso. valve rpl.	N/A	O	O	N	N/R	N					
7	7007 H&R Plant, 765 NW University Dr.	N	N	1965	1965	Visual inspection.	N/A	O	O	N	N/R	N					
8	7008 Waste Water Treatment Plant, 5620 New poa	N	N	1965	1965	Visual inspection/ Potholed.	N/A	O	P	N	N/R	N					
9	7009 ERTC, 5618 New Poag Rd.	N	N	1976	1976	Visual inspection/ Potholed.	N/A	O	O	N	N/R	N					
10	7011 Supporting Service Building, 99 Supporting Se	N	N	1970	1970	Visual inspection/ Potholed.	N/A	O	O	N	N/R	N					
11	7012 Water Tower, NW University Dr.	N	N	1965	1965	Visual inspection.	N/A	O	O	N	N/R	N					
12	7014 Religious Center, 81 Circle Dr	N	N	1971	1971	Visual inspection/ Potholed.	N/A	O	CLS	N	N/R	N					
13	7018 Founders Hall, 115 Peck Service Rd	N	N	1978	2019	Visual inspection/ Renovated 2019.	N/A	P	O	N	N/R	N					
14	7019 Alumni Hall, 125 Peck Service Rd.	N	N	1978	1978	Visual inspection/ Iso. valve rpl.	N/A	O	O	N	N/R	N					
15	7020 Radio Transmitter Building, 102 Supporting Se	N	N	1970	1970	Visual inspection/ Iso. valve rpl.	CLS	O	CLS	N	N/R	N					
16	7022 Edwardsville Fire Station, 783 NW University	N	N	2017	2017	Construction rec. per EDW. F.D.	N/A	C	C	N	N/R	N					
17	7023 Science Building, 44 Circle Dr.	N	N	2012	2012	Construction records.	N/A	P	O	N	N/R	N					
18	7026 Cougar Lake Pool, 80 Recreation Rd.	N	N	1973	1973	Visual inspection/ Iso. valve rpl.	N/A	P	CLS	N	N/R	N					
19	7030 Vadalabene Center, 35 Circle Dr	N	N	1983	1983	Visual inspection/ Iso. valve rpl.	N/A	P	O	N	N/R	N					
20	7030 Lukas Annex 35 Circle Dr.	N	N	2013	2013	Visual inspection/ Iso. valve rpl.	N/A	P	O	N	N/R	N					
21	7032 Recplex-Intramural Athletic Field, 780 NW Un	N	N	2003	2003	Construction records.	N/A	P	C	N	N/R	N					
22	7033 Metcalf Theater, 47 Circle Dr.	N	N	1984	1984	Visual inspection.	N/A	P	CLS	N	N/R	N					
23	7034 Early Childhood Center, 795 NW University Dr	Y	N	1986	1986	Visual inspection/ Iso. valve rpl.	N/A	O	O	N	N/R	N					
24	7035 Art&Design Building, 75 Circle Dr	N	N	1990	1990	Construction records.	N/A	P	O	N	N/R	N					
25	7036 Student Fitness Center, 35 Circle Dr.	N	N	1993	1993	Visual inspection/ Iso. valve rpl.	N/A	P	O	N	N/R	N					
26	7037 Engineering Building, 61 Circle Dr	N	N	2000	2000	Visual inspection/ Iso. valve rpl.	N/A	P	O	N	N/R	N					
27	7038 Woodland Hall, 95 Residence Hall Dr.	N	N	1995	1995	Visual inspection/ Iso. valve rpl.	N/A	P	O	N	N/R	N					

28	7039 Korte Stadium, 3345 Stadium Dr.	N	N	1994	1994	Visual inspection.	N/A	P	O	N	N/R	N					
29	7040 Greenhouse, 40 Hairpin Dr.	N	N	1998	1998	Visual inspection.	C	C	C	N	N/R	N					
30	7041 Prairie Hall, 50 Residence Hall Dr.	N	N	1998	1998	Visual inspection/ Iso. valve rpl.	N/A	P	O	N	N/R	N					
31	7042 Nature Preserve Field Station, 3690 Stadium Dr.	N	N	2013	2013	Visual inspection.	N/A	C	C	N	N/R	N					
32	7043 Bluff Hall , 60 Circle Dr	N	N	2000	2000	Construction records.	N/A	P	O	N	N/R	N					
33	7044 Ethanol Plant, 400 University Park Dr.	N	N	2001	2001	Visual inspection.	N/A	P	O	N	N/R	N					
34	7046 Evergreen Hall, 70 Circle Dr.	N	N	2007	2007	Visual inspection/ Iso. valve rpl.	N/A	P	O	N	N/R	N					
35	7047 Engineering West Building, 65 Circle Dr	N	N	2013	2013	Visual inspection/ Iso. valve rpl.	N/A	P	O	N	N/R	N					
36	7048 Art & Design West Building, 71 Circle Dr.	N	N	2013	2013	Construction records.	N/A	P	O	N	N/R	N					
37	7049 220 School of Pharmacy, 220 University Park Dr.	N	N	2005	2005	Visual inspection.	N/A	P	O	N	N/R	N					
38	7051 Technology & Management Center, 245 South 1st St.	N	N	2005	2005	Visual inspection	N/A	O	C	N	N/R	N					
39	7055 Student Success Center, 58 Circle Dr.	N	N	2009	2009	Visual inspection/ Iso. valve rpl.	N/A	P	O	N	N/R	N					
40	7137 Gardens Office Building, 6 Arboretum Ln.	N	N	2007	2007	Visual inspection.	C	C	C	N	N/R	N					
41	7144 Housing Maintenance Office, 350 Cougar Lake Dr.	N	N	1961	1961	Visual inspection.	N/A	P	CLS	N	N/R	N					
42	7161 Storage Pole Barn, 75 Whiteside Dr.	N	N	1995	1995	Visual inspection/ Valve closed.	N/A	P	C, line isolated.	N	N/R	N					
43	7185 Softball Club House, 3561 Stadium Dr.	N	N	1994	1994	Visual inspection.	N/A	P	C	N	N/R	N					
44	7190 Baseball Fields & Grounds (club house) 5200 N 1st St.	N	N	1994	1994	Visual inspection.	N/A	P	C	N	N/R	N					
45	7191 Baseball Fields & Grounds (concessions) 5200 N 1st St.	N	N	1994	1994	Visual inspection.	N/A	P	C	N	N/R	N					
46	7198 Library Storage Facility, 95 Supporting Service Dr.	N	N	2001	2001	Visual inspection.	N/A	P	O	N	N/R	N					
47	7199 University Museum Storage Building 103 Supporting Service Dr.	N	N	1998	1998	Visual inspection.	N/A	P	O	N	N/R	N					
48	7401/7402 Cougar Village Apartments, 401/402 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
49	7403 Cougar Village Apartments, 403 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
50	7404/7405 Cougar Village Apartments, 404/405 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
51	7406/7407 Cougar Village Apartments, 406/407 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
52	7408/7409 Cougar Village Apartments 408/409 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
53	7410 Cougar Village Apartments, 410 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
54	7411/7412 Cougar Village Apartments, 411/412 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
55	7413 Cougar Village Apartments, 413 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
56	7414/7415 Cougar Village Apartments, 414/415 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
57	7416/7417 Cougar Village Apartments, 416/417 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
58	7418/7419 Cougar Village Apartments, 418/419 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
59	7420 Cougar Village Apartments, 420 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
60	7421/7422 Cougar Village Apartments, 421/422 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
61	7423/7424 Cougar Village Apartments, 423/424 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
62	7425/7426 Cougar Village Apartments, 425/426 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
63	7427/7428 Cougar Village Apartments, 427/428 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
64	7429 Cougar Village Apartments, 429 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
65	7430/7431 Cougar Village Apartments, 430/431 Cougar Lake Dr.	N	N	1974	1974	Historical Records	N/A	O	CLS	N	N/R	N					
66	7501 Cougar Village Apartments, 501 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
67	7502 Cougar Village Apartments, 502 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
68	7503 Cougar Village Apartments, 503 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
69	7504 Cougar Village Apartments, 504 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
70	7505 Cougar Village Apartments, 505 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
71	7506 Cougar Village Apartments, 506 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
72	7507 Cougar Village Apartments, 507 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
73	7508 Cougar Village Apartments, 508 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
74	7509 Cougar Village Apartments, 509 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
75	7510 Cougar Village Apartments, 510 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
76	7511 Cougar Village Apartments, 511 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
77	7512 Cougar Village Apartments, 512 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
78	7513 Cougar Village Apartments, 513 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
79	7514 Cougar Village Apartments, 514 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
80	7515 Cougar Village Apartments, 515 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
81	7516 Cougar Village Apartments, 516 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
82	7517 Cougar Village Apartments, 517 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
83	7518 Cougar Village Apartments, 518 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
84	7519 Cougar Village Apartments, 519 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
85	7520 Cougar Village Apartments, 520 Cougar Lake Dr.	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					

86	7521 Cougar Village Apartments, 521 Cougar Lake	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
87	7522 Cougar Village Apartments, 522 Cougar Lake	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
88	7523 Cougar Village Apartments, 523 Cougar Lake	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
89	7524 Cougar Village Apartments, 524 Cougar Lake	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
90	7525 Cougar Village Apartments, 525 Cougar Lake	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
91	7526 Cougar Village Apartments, 526 Cougar Lake	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
92	7527 Cougar Village Apartments, 527 Cougar Lake	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
93	7528 Cougar Village Apartments, 528 Cougar Lake	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
94	7529 Cougar Village Apartments, 529 Cougar Lake	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
95	7530 Cougar Village Apartments, 530 Cougar Lake	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
96	7531 Cougar Village Apartments, 531 Cougar Lake	N	N	1975	1975	Visual inspection	N/A	O	P	N	N/R	N					
97	7532 Commons Building (cougar village) 500 Couga	N	N	1976	1976	Visual inspection.	N/A	P	CLS	N	N/R	N					
98	7532 200 University Park, 200 University Park Dr.	N	N	1990	1990	Construction records.	N/A	P	C	N	N/R	N					
99	7951 Dental Implant Clinic, 195 University Park Dr.	N	N	1997	1997	Visual inspection.	N/A	P	C	N	N/R	N					
100	7955 Admin Building, #1 North Research Dr.	N	N	1994	1994	Visual inspection.	C	P	C	N	N/R	N					
101	7957 Bio Tech Lab, 420 University Park Dr.	N	N	2005	2005	Visual inspection.	N/A	P	C	N	N/R	N					
102	7960 Juneau Associates, 100 North Research Dr.	N	N	1994	1994	Visual inspection.	N/A	P	C	N	N/R	N					
103	7961 Assurance Brokers LTC, 95 North Research Dr.	N	N	1996	1996	Visual inspection.	N/A	P	C	N	N/R	N					
104	7962 University Daycare, 47 North Research Dr.	Y	N	2000	2000	Visual inspection.	N/A	C	C	N	N/R	N					
105	7963 ESS Data Recovery, 110 North Research Dr.	N	N	1997	1997	Visual inspection.	N/A	P	C	N	N/R	N					
106	7980 Birger Foundation Building, 30 Circle Dr.	N	N	1999	1999	Visual inspection.	N/A	P	O	N	N/R	N					